



DOC NO.
PCN0107-01.0

Page 1 of 4

Product Change Notification

Change Notification #: PCN0107-01.0

Change Title: Optical Networking Components; IXF30005
IXF30007, IXF30009, IXF30010, IXF30011,
IXF30025, WB1400, WB1500, WB1501,
WB4500, & IXF25300 - Product Marking
Change

Date of Publication: January 17, 2007

Key Characteristics of the Change:
Product Marking

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	February 16, 2007
---	-------------------

Description of Change to the Customer:

In line with the recent acquisition of Intel's optical networking component product lines, Cortina Systems is announcing a product mark change. The Intel Corporation logo will be replaced by Cortina Systems, Inc. logo as shown below. Current Product Code and Material Master number (MM#) will not change. The product mark and/or pack you receive is not aligned to your order dates, but is dependant on Intel/Cortina first shipping out all Intel marked products.

Customer Impact of Change and Recommended Action:

This change has no impact on form, fit, functionality, customer handling, manufacturability, or product quality. Cortina does not anticipate impact to any customer applications. Until inventory is depleted, customers may receive either Intel or Cortina product mark. Please refer to the reference documents below for Cortina logo examples. Customers may want to notify their receiving department(s) for this change.



Products Affected / Intel Ordering Codes:

Product	MM #
ELWB1400.C1	876123
FLWB1400.C1	862140
ELWB1500.C1	876124
FLWB1500.C1	862141
ELWB1501.C1	876125
FLWB1501.C1	862142
HLWB4500.A0	857101
HLWB4500.B0	861182
WPWB4500.B0	876128
HLIXF25300BE.A1	862139
HLIXF25300BE.B0	869121
WPIXF25300BE.B0	885974
SSIXF30005	875250
TLIXF30005	852364
TLIXF30005	854060
SSIXF30007	875251
TLIXF30007	852838
SSIXF30009	875252
SSIXF30010	875253
SSIXF30011	875263
TLIXF30009	865852
TLIXF30010	865854
TLIXF30011	865853
SSIXF30025	875264
TLIXF30025	850332

Reference Documents / Attachments:


Document: **Location #:**



DOC NO.
PCN0107-01.0

Page 3 of 4

Product Top Side Mark
Example of current Intel mark





DOC NO.
PCN0107-01.0

Page 4 of 4

Product Top Side Mark
New Mark Example



PCN Revision History:

Date of Revision:
January 17, 2007

Revision Number:
00

Reason:
Originally Published PCN