



Product Change Notification

Change Notification #: PCN0107-04.0
Change Title: Optical Networking Division, IXF1010, IXF1110, & IXF1104 - Product Marking Change
Date of Publication: 24 January 2007

Key Characteristics of the Change:

Product Marking

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	24 February 2007
---	------------------

Description of Change to the Customer:

In line with the recent acquisition of Intel's optical networking component product lines, Cortina Systems is announcing a product mark change. The Intel Corporation logo will be replaced by Cortina Systems, Inc. logo as shown below. Current Product Code, S-Spec, and Material Master number (MM#) will not change. The product mark and/or pack you receive is not aligned to your order dates, but is dependant on Intel/Cortina first shipping out all Intel marked products.

Customer Impact of Change and Recommended Action:

This change has no impact on form, fit, functionality, customer handling, manufacturability, or product quality. Cortina does not anticipate impact to any customer applications. Until inventory is depleted, customers may receive either Intel or Cortina product mark. Please refer to the reference documents below for Cortina logo examples. Customers may want to notify their receiving department(s) for this change.



Products Affected / Intel Ordering Codes:


Product	MM #
HFIXF1010CC.B2	860741
WFIXF1010CC.B2	871327
HFIXF1104CE.B0	853714
HPIXF1104BE.B0	874579
WFIXF1104CE.B0	870726
WPIXF1104BE.B0	883991
WPIXF1104BE.B0	885094
HFIXF1110CC.B2	860817
WFIXF1110CC.B2	871328
HFST11060CC.B2	860742
WFST11060CC.B2	871329

Reference Documents / Attachments:


Document:

Location #:

Product Top Side Mark
Example of current Intel mark



Product Top Side Mark
New Mark Example





DOC NO.
PCN 0107- 04.0

Page 5 of 5

PCN Revision History:

Date of Revision:
24 January 2007

Revision Number:
00

Reason:
Originally Published PCN