



Customer Notification

Change Title: Optical Networking Components; IXF25300, IXF30005, IXF30009, IXF30025, WB1400, WB1500, WB1501 and WB4500; DCL200708-00; FYI - Minimum Order Quantity and Standard Increment Change

Date of Publication: 8 August 2007

Key Characteristics of the Change:

For Your Information - Order Quantity Requirements Change

Key Milestones:

Date New MoQ and SI Begin with Orders Received After:	30 September 2007
Date Customers with Annual Contracts MoQ and SI Increments Begin with Orders Received After:	31 December 2007

Description of Change to the Customer:

To improve our shipping cycle times and to reduce packaging waste, Cortina Systems is announcing a Minimum Order Quantity (MoQ) and Standard Increment (SI) change to the affected product list below. Orders received after 30 September 2007 will be required to meet MoQ and SI requirements. For Customers with annual contracts, orders received after 31 December 2007 will be required to meet MoQ and SI requirements.

Customer Impact of Change and Recommended Action:

This change has no impact on form, fit, functionality, customer handling, manufacturability, or product quality. Additionally, there will be no change to Product Code and/or MM#. Sample and prototype orders are exempt from the new MOQ's, please contact customerservice@cortina-systems.com if you need a waiver for these purposes.



Products Affected / Cortina Ordering Codes:

Affected Product Code	Media Type	Affected MM #	Previous MOQ	Previous Standard Increment	New MOQ	New Standard Increment
WPIXF25300BE.B0	TRAY	885974	10	1	27	27
HLIXF25300BE.B0	TRAY	869121	10	1	27	27
TLIXF30005	TRAY	854060	10	1	21	21
SSIXF30005	TRAY	875250	10	1	21	21
TLIXF30007	TRAY	852838	10	1	24	24
SSIXF30007	TRAY	875251	10	1	24	24
TLIXF30011	TRAY	865853	10	1	21	21
TLIXF30010	TRAY	865854	10	1	21	21
TLIXF30009	TRAY	865852	10	1	21	21
SSIXF30011	TRAY	875263	10	1	21	21
SSIXF30010	TRAY	875253	10	1	21	21
SSIXF30009	TRAY	875252	10	1	21	21
TLIXF30025	TRAY	850332	10	1	21	21
FLWB1400.C1	TRAY	862140	10	1	24	24
ELWB1400.C1	TRAY	876123	10	1	24	24
FLWB1500.C1	TRAY	862141	10	1	24	24
ELWB1500.C1	TRAY	876124	10	1	24	24
FLWB1501.C1	TRAY	862142	10	1	24	24
ELWB1501.C1	TRAY	876125	10	1	24	24
WPWB4500.B0	TRAY	876128	10	1	27	27
HLWB4500.B0	TRAY	861182	10	1	27	27

DCL Revision History:

Date of Revision:
8 August 2007

Revision Number:
00

Reason:
Originally Published DCL