



Customer Notification

Customer Notification #: DCL0108-01.0
Change Title: Networking Components; EPON, Ethernet, Framers, HSIO, Phy, T1/E1, & Transport; DCL0108-01.0; Product Code
Date of Publication: 04 January 2008

Reason for this notice:
Product Code Change

Description of Change to the Customer:

In line with our conversion into the Oracle Platform, Cortina Systems, Inc., is modifying our product code scheme effective immediately.

Cortina's previous order code had a separate field for the Material Master Number (MM#) as well as the Item Description Code.

Old Version Example:

Item Description Code	MM # (Item Number)
WJLXT972ALC.A4 857341	857341

The new Oracle Platform version will eliminate the redundancy of a separate numeric code which already exists as part of the item description.

New Oracle Platform Example:

New Order Code
WJLXT972ALC.A4-857341



DOC NO.
DCL0108-01.0

Page 2 of 2

Customer Impact of Change and Recommended Action:

This change has no impact on form, fit, functionality, customer handling, manufacturability, or product quality. Cortina does not anticipate impact to any customer applications.

Customers may continue to order using the same part numbers they use today, or change to the new order codes. Our documentation (order acknowledgment, packing slips, etc.) will no longer carry the separate MM#.

Customers may want to notify their receiving department(s) of this change.

Please contact your local Cortina Sales Representative for further information.

DCL Revision History:

Date of Revision:

04 January 2008

Revision Number:

0

Reason:

Originally Published PCN