



Product Change Notification

Change Notification #: PCN0407-01.0
Change Title: Immenstar IS8010, IS8015, IS8015A, IS8020, IS8020A, & IS8030 - Product Marking Change
Date of Publication: 10 April 2007

Key Characteristics of the Change:

Product Marking

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	10 May 2007
---	-------------

Description of Change to the Customer:

In line with the recent acquisition of Immenstar's product lines, Cortina Systems is announcing a product mark change. The Immenstar Corporation logo will be replaced by Cortina Systems, Inc. logo as shown below. In addition the current Product Code and Material Master number (MM#) will change. The product mark and/or pack you receive is not aligned to your order dates, but is dependant on Immenstar/Cortina first shipping out all of Immenstar marked products.

Customer Impact of Change and Recommended Action:

This change has no impact on form, fit, functionality, customer handling, manufacturability, or product quality. Cortina does not anticipate impact to any customer applications. Until inventory is depleted, customers may receive either Immenstar or Cortina product mark. Please refer to the reference documents below for Cortina logo examples. Customers may want to notify their receiving department(s) for this change.



Products Affected / Cortina Ordering Codes:

Affected Product Code	Post-Conversion Product Code	Post-Conversion MM#
IS8010	PCCS8016E.A0	998420
IS8015	PCCS8015E.A1	998440
IS8015A	PCCS8016E.A0	998420
IS8020	EWCS8020C.A1	998430
IS8020A	EWCS8021C.A0	998410
IS8020A	EWCS8021C.A1	998400
IS8030	EWCS8021C.A1	998400

Reference Documents / Attachments:

Document:

Location #:

Product Top Side Mark

Example of current Immenstar mark





Product Top Side Mark

New Mark Example



PCN Revision History:

Date of Revision:
10 Apr 2007

Revision Number:
00

Reason:
Originally Published PCN