



# Product Change Notification

**Change Notification #:** PCN0707-06.0  
**Change Title:** Optical Networking Components; IXF1012, IXF1024, IXF18101, IXF18102, IXF18103, IXF18104, IXF18105, IXF18201, IXF18203, IXF19301, IXF19302, IXF19303, & IXF19325  
PCN0707-06.0; Product Marking Change

**Date of Publication:** 23 July 2007

## Key Characteristics of the Change:

Product Marking

## Forecasted Key Milestones:

<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	22 August 2007
---	----------------

## Description of Change to the Customer:

### Reason for Revision: Product Marking Change Update

Cortina Systems is announcing a product mark change revision. The current product code and material master number (MM#) will not change. The Cortina Lot Number and Master Copyright symbol will be added.

The "Date Customer Must Be Ready To Receive Post-Conversion Material" is the projected date that a customer may expect to receive the Post-Conversion Materials. This date is determined by the projected depletion of inventory at the time of the PCN publication. The depletion of inventory may be impacted by fluctuating supply and demand, therefore, although customers should be prepared to receive the Post-Converted Materials on this date, Cortina Systems will continue to ship and customers may continue to receive the pre-converted materials until the current inventory has been depleted.

## Customer Impact of Change and Recommended Action:

This change has no impact on form, fit, functionality, customer handling, manufacturability, or product quality. Cortina does not anticipate impact to any customer applications. Until inventory is depleted, customers may receive either Cortina product mark. Please refer to the reference documents below for Cortina logo examples. Customers may want to notify their receiving department(s) for this change.



Please contact your local Cortina Sales Representative for further information regarding this product.

**Products Affected / Cortina Ordering Codes:**

Affected Product Code	Affected MM #
GCIXF1012EC.A3	884560
GCIXF1024EC.A3	884561
GCIXF18101EE.B0	853146
GCIXF18102EE.B0	853147
GCIXF18103EE.B0	853148
GCIXF18103L.B0	880096
GCIXF18104EE.B0	853149
GCIXF18105EC.B1	884472
GCIXF18201EC.B1	886340
GCIXF18203EC.B1	884471
GCIXF19301EE.B1	885703
GCIXF19302EE.B1	885706
GCIXF19303EE.B1	885705
GCIXF19325EE.B1	885707
TLIXF30025	850332



Product Top Side Mark

Current Mark Example



**PART NAME REV**

**CORTINA FPO**

**CORTINA (C) YEAR**

**TAIWAN**



DOC NO.  
PCN0707-06.0

Page 4 of 4

Product Top Side Mark

New Mark Example



**PCN Revision History:**

**Date of Revision:**  
23 July 2007

**Revision Number:**  
0

**Reason:**  
Originally Published PCN