



## Product Change Notification

**Document #:** PCN400628  
**Change Title:** Cortina Systems – Product Material Change, IXF1024, IXF18101, IXF18201 & IXF19301 Family, FYI, PCN400628  
**Revision Date:** July 7, 2008

### Type of Change Notification:

FYI (For Your Information)

### Key Characteristics of the Change:

Product Material

### Forecasted Key Milestones:

<b>Date of First Availability of Post-Conversion Material:</b>	15 August 2008
<b>Date Customer Must be Ready to Receive Post-Conversion Material:</b>	15 August 2008

### Description of Change to the Customer:

As part of Continuous improvement of manufacturing process control, Cortina Systems will be changing the fill compound used during the assembly of these products. This change has resulted in improved process control at assembly.

### Customer Impact of Change and Recommended Action:

This change has no impact to the form, fit, or functionality. Cortina does not anticipate impact to any customer applications. Customers may receive product with either fill compounds until inventory has been depleted. There will be no change to the product ordering code.

Please contact your local Cortina Sales Representative for further information regarding this PCN.

## Products Affected / Cortina Systems Ordering Codes:

Affected Family Name	Affected Product Code	Affected MM#	Media Type
IXF1024	GCIXF1012EC.A3-884560	884560	TRAY
IXF1024	GCIXF1024EC.A3-884561	884561	TRAY
IXF1024	QCIXF1024EC.A3-884612	884612	TRAY
IXF1024	QCIXF1012EC.A3-884616	884616	TRAY
IXF18101	GCIXF18101EE.B0-853146	853146	TRAY
IXF18101	GCIXF18102EE.B0-853147	853147	TRAY
IXF18101	GCIXF18103EE.B0-853148	853148	TRAY
IXF18101	GCIXF18104EE.B0-853149	853149	TRAY
IXF18101	GCIXF18103LEE.B0-880096	880096	TRAY
IXF18201	GCIXF18203EC.B1-884471	884471	TRAY
IXF18201	GCIXF18105EC.B1-884472	884472	TRAY
IXF18201	GCIXF18201EC.B1-886340	886340	TRAY
IXF18201	QCIXF18203EC.B1-998500	998500	TRAY
IXF18201	QCIXF18201EC.B1-998510	998510	TRAY
IXF18201	QCIXF18105EC.B1-998520	998520	TRAY
IXF19301	GCIXF19301EE.B1-885703	885703	TRAY
IXF19301	GCIXF19303EE.B1-885705	885705	TRAY
IXF19301	GCIXF19302EE.B1-885706	885706	TRAY
IXF19301	GCIXF19325EE.B1-885707	885707	TRAY

## Revision History

<b>Revision 1.0</b> <b>Revision Date: 20 June 2008</b>
Original Release - July 7, 2008

## **Cortina Systems, Inc. Confidential**

This document contains information proprietary to Cortina Systems, Inc. (Cortina). Any use or disclosure, in whole or in part, of this information to any unauthorized party, for any purposes other than that for which it is provided is expressly prohibited except as authorized by Cortina in writing. Cortina reserves its rights to pursue both civil and criminal penalties for copying or disclosure of this material without authorization.

**INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH CORTINA SYSTEMS® PRODUCTS.**

**NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT.**

**EXCEPT AS PROVIDED IN CORTINA'S TERMS AND CONDITIONS OF SALE OF SUCH PRODUCTS, CORTINA ASSUMES NO LIABILITY WHATSOEVER, AND CORTINA DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY RELATING TO THE SALE AND/OR USE OF CORTINA PRODUCTS, INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.**

Cortina products are not intended for use in medical, life saving, life sustaining, critical control or safety systems, or in nuclear facility applications.

Cortina Systems® and the Cortina Systems logo are the trademarks or registered trademarks of Cortina Systems, Inc. and its subsidiaries in the U.S. and other countries. Other names and brands may be claimed as the property of others.

Copyright © 2008 Cortina Systems, Inc. All rights reserved.

## **Contact Information**

**Cortina Systems, Inc.**  
840 W. California Ave  
Sunnyvale, CA 94086

408-481-2300

[sales@cortina-systems.com](mailto:sales@cortina-systems.com)  
[www.cortina-systems.com](http://www.cortina-systems.com)